



10/694830

wp c \$

THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

KANAO et al

Atty. Ref.: 2635-188

Patent No. 6,885,137 B2

Issued: April 26, 2005

For: SPARK PLUG AND ITS MANUFACTURING METHOD

Certificate

MAY 24 2005

of Correction

* * * * *

May 18, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR A CERTIFICATE OF CORRECTION
UNDER 37 C.F.R. §1.323 – APPLICANT'S MISTAKE

Pursuant to 37 C.F.R. §1.323, it is respectfully requested that Figures 11A and 11B of the above-identified issued patent be replaced by corrected Figures 11A and 11B as depicted on the attached Form PTO-1050. As is evident throughout the specification and in the brief description of Figures 11A and 11B at column 5, lines 15-21, the firing tip 55 in each of these Figures should be of octagonal shape. Accordingly, this minor drafting error is believed to be properly corrected by Certificate of Correction as now requested.

05/19/2005 SSITHIB1 00000046 6885137

01 FC:1811

100.00 DP


MAY 24 2005

KANAO et al
Patent No. 6,885,137 B2

The fee under 37 C.F.R. §1.20(a) of \$100.00 for this requested Certificate is
attached.

Respectfully submitted,

NIXON & VANDERHYE P.C.

By: 
Larry S. Nixon
Reg. No. 25,640

LSN:vc
901 North Glebe Road, 11th Floor
Arlington, VA 22203-1808
Telephone: (703) 816-4000
Facsimile: (703) 816-4100

MAY 24 2005

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,885,137 B2
DATED : April 26, 2005
INVENTOR(S) : KANAO et al

It is certified that error appears in the above-identified patent and that said letters patent is hereby corrected as shown below:

11 / 12

FIG. 11A





FIG. 11B



MAILING ADDRESS OF SENDER:

Larry S. Nixon
NIXON & VANDERHYE P.C.
901 North Glebe Road, 11th Floor
Arlington, Virginia 22201

PATENT NO.

6,885,137 B2

No. of addi
© 50¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,885,137 B2
DATED : April 26, 2005
INVENTOR(S) : KANAO et al

It is certified that error appears in the above-identified patent and that said letters patent is hereby corrected as shown below:

11/12

FIG. 11A





FIG. 11B



MAILING ADDRESS OF SENDER:

Larry S. Nixon
NIXON & VANDERHYE P.C.
901 North Glebe Road, 11th Floor
Arlington, Virginia 22201

PATENT NO. 6,885,137 B2

No. of addi-
@ 50¢ per page

MAY 24 2005

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,885,137 B2
DATED : April 26, 2005
INVENTOR(S) : KANAO et al

It is certified that error appears in the above-identified patent and that said letters patent
is hereby corrected as shown below:

11 / 12

FIG. 11A





FIG. 11B



MAILING ADDRESS OF SENDER:

Larry S. Nixon
NIXON & VANDERHYE P.C.
901 North Glebe Road, 11th Floor
Arlington, Virginia 22201

PATENT NO.

6,885,137 B2

No. of addi'
@ 50¢ per page

MAY 24 2005